LOAN DOCUMENT

		PHOTOGRAPH THIS	SHEET
DTIC ACCESSION NUMBER	LEVEL	DOCUMENT IDENTIFICATION Dec 94	
		DISTRIBUTION STA Approved for Publi Distribution Uni	c Release
/		DISTRIBUTIO	JA GIALBALIA
NTIS GRAME DTIC TRAC UNANNOUNCED JUSTIFICATION BY DISTRIBUTION/ AVAILABILITY CODES DISTRIBUTION AVAILABILITY AND/OR SPECIAL DISTRIBUTION STAMP			DATE ACCESSIONED A
			DATE RETURNED
20001127			
DATE REC	EIVED IN DTIC		REGISTERED OR CERTIFIED NUMBER
	PHOTOGRAPH T	HIS SHEET AND RETURN TO DTIC-FD	DAC
DTIC POPM 70A		DOCTOVENT PROCESSING SUPET	PREVIOUS EDITIONS MAY BE USED UNTIL

DTIC JUN 90 70A

LOAN DOCUMENT

STOCK IS EXHAUSTED.

PART I

Bioventing Pilot Test Work Plan for Site 13115 Heating Oil UST Site Marine Corps Base Camp Pendleton, California

PART II

Draft Bioventing Pilot Test Interim
Results Report for
Site 13115
Heating Oil UST Site
Marine Corps Base Camp Pendleton, California

Prepared For

Air Force Center for Environmental Excellence Brooks AFB, Texas

and

ACS Environmental Security
MCB Camp Pendleton, California

Parsons ES

Parsons Engineering Science, Inc.

December 1994

9404 Genesee Avenue, Suite 140 La Jolla, California 92037

	REQUEST FOR SCIENTIFIC AND	TECHNICAL REPO	RTS	
Title AFCEE Collection				
Ľ	Manufacture and American Ameri	***************************************		
	Report Availability (Please check one box)	2a. Number of Copies Forwarded	2b. Forwarding Date	
I X	This report is available. Complete sections 2a - 2f. This report is not available. Complete section 3.		0 (
	Distribution Statement (Please check ONE box)	Leach	July/2000	
	Directive 5230.24, "Distribution Statements on Technical Documents."	* 18 Mar 87 contains sover	Cilerribution statements as	
des	scribed briefly below. Technical documents MUST be assigned a distrib	oution statement.	rdiscribation statements, as	
M	DISTRIBUTION STATEMENT A: Approved for public reli	ease. Distribution is u	nlimited.	
	DISTRIBUTION STATEMENT B: Distribution authorized	to U.S. Government A	Agencies only.	
	DISTRIBUTION STATEMENT C: Distribution authorized contractors.	to U.S. Government A	Agencies and their	
	DISTRIBUTION STATEMENT D: Distribution authorized DoD contractors only.	to U.S. Department of	Defense (DoD) and U.S	
	DISTRIBUTION STATEMENT E: Distribution authorized components only.	to U.S. Department of	Dafensa (DoD)	
	DISTRIBUTION STATEMENT F: Further dissemination of indicated below or by higher authority.	mly as directed by the	controlling DoD office	
	DISTRIBUTION STATEMENT X: Distribution authorized to U.S. Government agencies and private individuals or enterprises eligible to obtain export-controlled technical data in accordance with DoD Directive 5230.25, Withholding of Unclassified Technical Data from Public Disclosure, 6 Nov 84.			
2d.	Reason For the Above Distribution Statement (in accord	lance with BoD Directive 5.	230.24)	
2e.	Controlling Office	2f. Date of Distri	bution Statement	
	HQ AFLEE	Determination 15 Nov	2000	
₹	This report is NOT forwarded for the following reasons	· (Please check appropris	oto box)	
	It was previously forwarded to DTIC on(da			
	It will be published at a later date. Enter approximate date	•	······································	
	In accordance with the provisions of DoD Directive 3200.1 because:	**********	ment is not supplied	
	and the state of t	and the state of t	110000000000000000000000000000000000000	
		g(+2]41-447-1-1-7-243-10-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		
Derāvo	it or Type Name Signate			
10	Signal Signal	ure)	
	phone	(FOT UTIC USE OF		
21	10-536-1431	AQ Number //	101-01-0304	

PART I

Bioventing Pilot Test Work Plan for Site 13115 Heating Oil UST Site Marine Corps Base Camp Pendleton, California

PART II

Draft Bioventing Pilot Test Interim
Results Report for
Site 13115
Heating Oil UST Site
Marine Corps Base Camp Pendleton, California

Prepared For

Air Force Center for Environmental Excellence Brooks AFB, Texas

and

ACS Environmental Security
MCB Camp Pendleton, California

Parsons ES

Parsons Engineering Science, Inc.

December 1994

CONTENTS

PART I BIOVENTING PILOT TEST WORK PLAN SITE 13115 HEATING OIL UST MARINE CORPS BASE CAMP PENDLETON, CALIFORNIA

		Page
1.0	INTRODUCTION	I-1
2.0	SITE DESCRIPTION	
2.1	Site Location and History	I-3
2.2	Site Geology	I-3
2.3	Site Contaminants	I-3
3.0	SITE-SPECIFIC ACTIVITIES	I-6
3.1	Location and Construction of Vent Wells and	
	Vapor Monitoring Points	I-6
3.2	Handling of Drill Cuttings	I-9
3.3	Soil and Soil Gas Sampling	I-9
	3.3.1 Soil Samples	I-9
	3.3.2 Soil Gas Samples	I-11
3.4	Blower System	I-11
3.5	In-Situ Respiration Test	I-11
3.6	Air Permeability Test	I-13
3.7	Air Emissions Monitoring	I-13
3.8	Installation of Extended (One-Year) Pilot Test	
	Bioventing System	I-13
4.0	EXCEPTIONS TO PROTOCOL PROCEDURES	I-14
5.0	BASE SUPPORT REQUIREMENTS	I-14
6.0	PROJECT SCHEDULE	I-15
7.0	POINTS OF CONTACT	I-15
8.0	REFERENCES	I-16

FIGURES

Figure	Description	Page
1.1	MCB Camp Pendleton Location Map	I-2
2.1	Site Location Map and Proposed Vent Well/Vapor Monitoring Point Location, Site 13115 Heating Oil UST	I-4
2.2	Geological Cross section A-A, Site 13115 Heating Oil UST	I-5
3.1	Proposed Deep Air Injection Vent Well Construction Details, Site 13115 Heating Oil UST	I-7
3.2	Proposed Shallow Air Injection Vent Well Construction Details, Site 13115 Heating Oil UST	I-8
3.3	Proposed Monitoring Point Construction Details, Site 3115 Heating Oil UST	I-10
3.4	Blower System Instrumentation Diagram for Air Injection, Site 13115 Heating Oil UST	I-12

PART I

BIOVENTING PILOT TEST WORK PLAN FOR SITE 13115 HEATING OIL UST SITE MARINE CORPS BASE CAMP PENDLETON, CALIFORNIA

1.0 INTRODUCTION

This Pilot Test Work Plan presents the scope of an *in-situ* bioventing pilot test for the treatment of fuel-contaminated soils at the Building 13115 heating oil underground storage tank (UST) site, located in Area 13 on Marine Corp Base (MCB) Camp Pendleton. Camp Pendleton is located almost entirely in northern San Diego County (Figure 1.1), approximately halfway between Los Angeles and San Diego. MCB Camp Pendleton is located on the Pacific Coast between the cities of San Clemente (in southern Orange County) to the north, Oceanside to the south, and Fallbrook to the east. Constructed in 1942, the Base is primarily used for amphibious training. Other important Base activities include a Marine Corps Air Station and several artillery and bombing ranges. Background information on MCB Camp Pendleton and on Building 13115 is derived from MCB Camp Pendleton, California, Underground Storage Tank Draft Site Assessment Report (Jacobs Engineering, IT Corp., CH2M Hill. April 1993).

Bioventing tests have three primary objectives: (1) to assess the potential for supplying oxygen throughout the contaminated soil interval, (2) to determine the rate at which indigenous microorganisms will degrade fuel in the soil when stimulated by oxygen-rich soil gas, and (3) to evaluate the potential for sustaining these rates of biodegradation until fuel contamination is remediated to concentrations below regulatory standards.

The pilot test will be conducted in two phases. The initial pilot test phase will include installation of a vent well (VW) and three vapor monitoring points (MPs), followed by an *in-situ* respiration test and an air permeability test. The initial pilot test will determine important design parameters such as air permeability, radius of influence, biodegradation rates, and potential air emission quantities. It is anticipated that the duration of this initial testing will be approximately two weeks. If initial testing proves successful, an extended (one-year) testing phase will be initiated which will determine the longer term application of this remedial technology to degrade hydrocarbons at the site.

If bioventing is determined to be feasible at this site, pilot test data could be used to design and implement a full-scale remediation system (if necessary), and to estimate the time required for site cleanup. Since testing will take place within the



most contaminated soil at the site, an added benefit of pilot testing is that a significant amount of the fuel contamination should be biodegraded during the extended (one-year) pilot tests.

Additional background information on the development and recent success of bioventing technology is found in the *Test Plan and Technical Protocol for a Field Treatability Test for Bioventing* (Hinchee et. al., 1992). This protocol document will also serve as the primary reference for pilot test well designs and the detailed procedures which will be used during the tests.

2.0 SITE DESCRIPTION

2.1 Site Location and History

Building 13115 is located near the southern boundary of MCB Camp Pendleton in Area 13, west of Vandergrift Boulevard, approximately three miles north of the Vandergrift gate. This two story, former barracks now houses administrative offices. Constructed on concrete pilings, Building 13115 sits approximately two feet above the ground surface.


A 1,000-gallon, single-walled concrete bottle-neck UST was installed in 1943. The tank stores heating oil for the building's furnace. In October 1986, this tank failed an integrity test. In late 1991 and early 1992, site characterization activities were performed by IT Corporation. Characterization activities included drilling and sampling nine borings, which ranged in depth from 20 to 56 feet below the ground surface (bgs). Soil samples for laboratory analysis were collected at five-foot intervals. Groundwater was not encountered at the site. The location of the heating oil tank and previous site characterization borings are shown in Figure 2.1.


2.2 Site Geology

Soils encountered during previous investigations were very dense sands, silty and clayey sands, silt and clay of the Santiago formation which is part of the La Jolla Group (Jacobs Engineering et. al. 1993). The La Jolla Group ranges in composition from moderate deepwater fine grain siltstones to sandy beach and continental sandstone and conglomerate of middle Eocene age. A geologic cross section of the site is presented on Figure 2.2. The cross section was developed from the boring logs of previous investigations and from the cross sections contained in the Underground Storage Tank Draft Site Assessment Report.

2.3 Site Contamination

Site contamination consists of heating oil that leaked from the 1,000 gallon concrete UST or associated piping, which is still in use at the site. Soil samples collected during the site assessment were analyzed for total recoverable petroleum hydrocarbons (TRPH) by EPA 418.1 only. The sample from 19 feet bgs in boring B13115-3 had the highest TRPH concentration of 12,619 mg/kg. Soil sample locations and results are shown on Figure 2.2.





3.0 SITE-SPECIFIC ACTIVITIES

The purpose of this section is to describe the bioventing test that will be performed by ES, at Building 13115. Activities at the site will include: (1) siting and construction of a central air injection VW system, and four vapor MPs; (2) an air permeability test; (3) an *in-situ* respiration test; and (4) the implementation of an extended (one-year) bioventing pilot test. Soil and soil gas sampling procedures are described below. In addition, the blower configuration that will be used to inject ambient air into contaminated soils through the VW is also discussed in this section. No dewatering or groundwater treatment will take place during the pilot test. Pilot test activities will be confined to the remediation of unsaturated soils.


3.1 Location and Construction of Vent Wells and Vapor Monitoring Points

A general description of criteria for siting a VW and MPs are included in the protocol document. Because of the site geology, a two well VW system will be constructed. Figure 2.1 an 2.2 indicate the proposed locations of the VW system and MPs at this site. The final locations of the VW system and MPs may vary slightly from the proposed locations if significant fuel contamination is not observed in the boring for the VWs. The VW system will be located in the area of highest detected fuel contamination (based on previous site investigation sampling data). This area is expected to have TPH concentration of up to 12,000 mg/kg. Soils in this area are expected to be oxygen-depleted (<2 percent O₂) and increased biological activity should be stimulated by oxygen-rich soil gas ventilation during extended pilot test operations.

Based on previous site characterization information, soil contamination extends radially, approximately 80 feet from the heating oil UST. The radius of venting influence in the sandier soil around the VW is estimated to be 60 feet. The venting radius in the clay near the surface will be somewhat less. Three MPs will be located within a 70 foot radius of the VW system in contaminated soil if possible. A fourth MP will be located approximately 300 feet north of the VW system. This background MP will be used to measure background levels of oxygen and carbon dioxide at the base, and to determine whether inorganic or natural carbon sources are contributing to oxygen uptake during the *in-situ* respiration test. Additional details of the *in-situ* respiration test are found in Section 5.7 of the protocol document.

A single vent well screened through the contaminated soil interval would direct most of the airflow through the sandier soil below 15 feet bgs. This would leave the majority of the clay from the ground surface to 15 feet bgs unaffected by air injection. To more effectively deliver oxygen through the clay, ES will use a 2 well VW system. One VW will be screened through the entire zone of soil contamination. A second VW will be screened through the clay only.

Construction diagrams for the VWs are shown in figures 3.1 and 3.2. A cross section of the VWs is shown on Figure 2.2 The VWs will be constructed of four-inch ID Schedule 40 PVC, with an interval of 0.04-inch slotted screen set at a depth of approximately six feet bgs or at the top of the contaminated soil interval. The screen of the deep VW will extend 36 feet to the base of contamination as determined by previous site characterization work. The screen of the shallow VW




PARSONS ENGINEERING SCIENCE, INC.

OFFICES IN PRINCIPAL CITIES

PARSONS

10 DESIGNED BY:
LD

PROPOSED DEEP AIR INJECTION
VENT WELL CONSTRUCTION DETAIL
SITE 13115 — HEATING OIL UST
MCB CAMP PENDLETON, CALIFORNIA



PARSONS ENGINEERING SCIENCE, INC.
OFFICES IN PRINCIPAL CITIES

PARSONS

9404 GENESEE AVENUE • SUITE 140 LA JOLLA, CA 92037 • (619) 453-9650 DESIGNED BY:
LD
DRAWN BY:
MSB
DATE:
12/13/94

FIGURE 3.2

PROPOSED SHALLOW AIR INJECTION VENT WELL CONSTRUCTION DETAIL

SITE 13115 — HEATING OIL UST MCB CAMP PENDLETON, CALIFORNIA

will extend to 15 feet bgs, the base of the clay. A GasTechTM Total Hydrocarbon Vapor Analyzer (THVA) will be used to collect field OVA readings for soil samples collected during drilling activities. This platinum catalyst combustion detector is calibrated with hexane, which provides a conservative reading representative of total volatile hydrocarbon (TVH) vapors present. Flush-threaded PVC casing and screen will be installed without using organic solvents or glues. The filter pack will consist of clean, 4-12 grain size (or equivalent) silica sand, and will be placed in the annular space of the screened interval. A two-foot-thick layer of bentonite pellets, hydrated in place with potable water, will be placed directly over the filer pack. This layer will prevent the Type A concrete from saturating the filter pack. The concrete will be tremied into the annular space above the bentonite pellets to a depth of one foot bgs, thus producing an air-tight seal above the screened interval. A complete seal is critical to prevent injected air from short-circuiting to the surface during the bioventing test.

A typical, multi-depth MP installation for this site is shown in Figure 3.3 and in Figure 2.2. Oxygen and carbon dioxide soil gas concentrations will be monitored via vapor monitoring screens placed at depth intervals of 6 feet, 12 feet, 18 feet, 25 feet and 35 feet bgs which correspond to the different soil types encountered during previous investigations. Multi-depth monitoring will assess whether the entire soil profile is receiving oxygen and will be used to measure fuel biodegradation rates at all monitored depths. The annular space between the vapor monitoring screen filter packs will be sealed with bentonite chips completely hydrated in place to isolate the monitoring intervals. As with the VWs, several inches of bentonite pellets will be used directly above and below the filter pack intervals for seals. In the vapor monitoring point closest to the VWs, thermocouples will be installed at the deepest and shallowest vapor monitoring screens to measure soil temperatures. Additional details on VW and MP construction are found in Section 4 of the protocol document.


3.2 Handling of Drill Cuttings

Drill cuttings will be collected in U.S. Department of Transportation (DOT) approved containers. These containers will be labeled, then placed in the area designated by the base point-of-contact. Final disposition of drill cuttings will be the responsibility of MCB Camp Pendleton, or their designated contractor.

3.3 Soil and Soil Gas Sampling

3.3.1 Soil Samples

Three soil samples will be collected from the pilot test area during the installation of the VW and MPs. Sampling procedures will follow those outlined in the protocol document. A total hydrocarbon vapor analyzer (THVA) will be used during drilling to screen soil samples for determining intervals of high fuel contamination. One sample will be collected from the most contaminated interval of each soil type. These soil samples will be analyzed for Total Recoverable Petroleum Hydrocarbons (TRPH); Benzene, Toluene, Ethylbenzene, and Xylenes (BTEX); and soil moisture, pH, grain-size distribution, alkalinity, total iron, and nutrients, including Total Kjeldahl Nitrogen (TKN) and total phosphorous.



An additional soil sample will be collected from representative soils in the background MP and analyzed for Total Kjeldahl Nitrogen (TKN) in order to characterize the non-contaminated, baseline soil nutrient conditions.

Soil samples will be collected using a split-spoon sampler containing brass tube liners. Sample tube ends will be sealed with Teflon sheets and held in place by plastic caps. Soil samples will be labelled following the nomenclature specified in the Section 5 of the protocol document, wrapped in plastic, and placed in a cooler for shipment. A chain-of-custody form will be completed, and the cooler will be shipped to Pace Laboratory in Huntington Beach, California, for analysis. This laboratory has been audited by the Air Force and meets all quality assurance/quality control (QA/QC) and certification requirements for the State of California.

3.3.2 Soil Gas Samples

During the pilot test, initial soil gas samples will be collected in SUMMA canisters, in accordance with the Bioventing Field Sampling Plan (ES, 1992). These samples will be collected from the VW, and from the MPs closest to and furthest from the VW (i.e., MPA and MPC). The soil gas samples will be used to predict potential air emissions, to determine the reduction in BTEX and Total Volatile Hydrocarbons (TVH) during the one-year tests, and to detect any migration of these vapors from the source areas.

Soil gas sample canisters will be placed in a small cooler and packed with foam pellets to prevent excessive movement during shipment. In order to prevent condensation of hydrocarbons, samples will not be preserved on ice. A chain-of-custody form will be completed, and the cooler will be shipped to the Air Toxics, Inc., laboratory in Folsom, California, where the samples will be analyzed by EPA method TO-3.


3.4 Blower Systems

A 1-horse power regenerative blower, capable of injecting 50 standard cubic feet per minute (scfm) at 40 inches of water will be used to conduct the initial air permeability test.

A schematic diagram of a typical air injection system used for pilot testing is shown on Figure 3.4. The maximum power requirement anticipated for this pilot test is 230-volt, single-phase, 30-amp service. Additional power supply requirement details are described in Section 5.0, Base Support Requirements.

3.5 In-Situ Respiration Tests

The objective of *in-situ* respiration tests is to determine the rate at which soil bacteria degrade petroleum hydrocarbons in the presence of oxygen. Respiration tests will be performed at MP screens, where bacterial biodegradation of hydrocarbons is indicated by low oxygen levels and elevated carbon dioxide concentrations in the soil gas. The test will be conducted in the MP screens with the highest TVH levels and lowest oxygen levels. Small 1 scfm pumps will inject air into selected MP screen intervals containing low oxygen levels (<2%). A 20-hour air injection period will be used to oxygenate local contaminated soils. At the end of the 20-hour air injection period, the air supply will be cut off, and oxygen and



PI PRESSURE INDICATOR

TI) TEMPERATURE INDICATOR

(VI) VACUUM INDICATOR

FCV FLOW CONTROL VALVE

FRV PRESSURE RELIEF VALVE

VRV VACUUM RELIEF VALVE

PARSONS ENGINEERING SCIENCE, INC.

OFFICES IN PRINCIPAL CITIES

PARSONS

9404 GENESEE AVENUE • SUITE 140 LA JOLLA, CA 92037 • (619) 453-9650 DESIGNED BY:

LD

DRAWN BY:

MSB

DATE:

12/13/94

FIGURE 3.4

BLOWER SYSTEM
INSTRUMENTATION DIAGRAM FOR AIR INJECTION
SITE 13115 — HEATING OIL UST
MCB CAMP PENDLETON, CALIFORNIA

carbon dioxide levels will be monitored for the following 48 to 72 hours. The decline in oxygen concentrations over time will be used to estimate rates of bacterial degradation of fuel residuals. Helium, an inert gas, will be injected at a concentration to two to four percent into every MP screen that is being used for respiration testing. The helium will be used as a tracer gas and levels will be monitored during the respiration test to identify possible system leaks or short circuits to the surface. Additional details on the *in-situ* respiration test are found in Section 5.7 of the protocol document

3.6 Air Permeability Tests

The objective of air permeability tests is to determine the areal extent of the subsurface soils (radius of influence) that can be oxygenated using one air injection VW. Air will be injected into the deep VW using a 1-horse power blower unit. Pressure response will be measured for 4 to 6 hours at each MP with differential pressure gauges to determine the regional influenced by the unit. Oxygen will also be monitored in the MPs over a period of 20 hours to verify that oxygen levels in the soil increase as the result of air injection. If, after 20 hours, oxygen levels in the clay do not increase, air flow from the blower will be diverted from the deep VW to the shallow VW soil. Oxygen concentrations will be monitored over the next few days and flow rates will be adjusted accordingly to ensure sufficient oxygen is being delivered through both clay and sandier soils.

3.7 Air Emissions Monitoring

Soil gas will not be extracted from the site during either the initial or extended pilot test. The proposed bioventing system will use a low rate (<30 scfm) of air injection to provide oxygen for enhanced biodegradation. Because these soils are contaminated with low-volatility heating oil, the potential for volatile emissions is very low. Because horizontal permeability is generally greater than vertical permeability, the injected air will tend to move outward rather than upward. This will promote *in-situ* biodegradation of fuel vapor as it moves slowly outward from the center of the spill.

If some upward movement of injected air does occur, it will be highest during the first day of air injection when the initial soil gas volume is displaced. ES will carefully monitor the air in the breathing zone during the first day of testing. A photoionization detector (PID) will be used to detect any emissions exceeding ambient conditions. The PID will be calibrated with isobutylene to detect BTEX compounds at the 1 ppmv level. This level of detection is consistent with the most conservative OSHA standards. Any sustained PID reading in excess of 1 ppmv will require an immediate reduction in air injection rates.

3.8 Installation of Extended (One-Year) Pilot Test Bioventing System

The extended (one-year) bioventing pilot test system will be installed at Building 13115 UST site if the initial pilot tests successfully demonstrate the feasibility of providing oxygen throughout the contaminated soil profile. Continued air injection would determine the long-term radius of oxygen influence, and the effects of time, available nutrients, and changing temperatures on fuel biodegration rates. As part of extended pilot test systems, a fixed blower unit will be installed in the boiler room

located near the heating oil UST. A 2-inch diameter PVC pipe will be buried approximately 6 inches underground and will run from the blower to the vent well. The blower will deliver air to the vent wells at a total flow rate of approximately 30 scfm. A system will be operated for one year. Every six months, ES personnel will conduct in-situ respiration tests to monitor the long-term performance of the bioventing system. In addition, subsurface soil and soil gas samples will be collected after one year at locations as close as possible to the original MP/VW soil and soil gas sample locations in order to assess the degree of remediation achieved during the first year of in-situ treatment. Weekly system checks will be performed by MCB Camp Pendleton personnel. If required, major maintenance of the blower unit will be performed by ES San Diego personnel. Detailed blower system information, and a maintenance schedule, will be included in the operation and maintenance (O&M) manual provided to the base. More detailed information regarding the test procedures are included in the protocol document.

4.0 EXCEPTIONS TO PROTOCOL PROCEDURES

Procedures used to construct MP and VWs, measure soil permeability to air, and measure *in-situ* respiration rates, are described in Sections 4 and 5, respectively, of the protocol document. An expected exception to the protocol document is the use of two VWs.

5.0 BASE SUPPORT REQUIREMENTS

To prevent further site contamination, ES recommends the base pump out the heating oil from the UST immediately.

The following base support is needed prior to arrival of the drilling subcontractor and the ES pilot test team:

- Coordinating this work plan with local regulatory agencies and advising if any additional permits or information are required.
- Obtaining a base digging permit.
- Confirmation of an available power source, and the installation of a 230-volt, 30-amp, single-phase breaker box with one 230-volt receptacle and two 110-volt receptacles located in or near the boiler room.
- Provision of any paperwork required to obtain gate passes and security badges for approximately three ES employees, three drillers, and an electrician (if a base electrician is not available). Vehicle passes will be needed for approximately three to four vehicles.
- Provision of keys to the boiler room.

During initial testing, the following base support is needed:

■ Acceptance of responsibility for drill cuttings from VW and MP borings, including any drum sampling to determine hazardous waste status. (If ES transfers custody of drums to another contractor working on the base, assistance in arranging this transfer will also be needed).

During the one-year extended pilot tests, base personnel will be required to perform the following activities:

- Check the blower system once per week to ensure that it is operating, and to record the air injection pressure and temperature, and to change the air filter as needed. ES will provide a brief training session for this procedure and a maintenance procedures manual with data collection sheets.
- If the blower stops working, notify: Mr. Larry Dudus of ES San Diego at (619) 453-9650, Mr. Chris Pluhar of ES Pasadena at (818) 585-6324, or Mr. Patrick Haas of AFCEE at (210) 536-4314.
- Arrange site access for an ES technician to conduct *in-situ* respiration tests approximately six months and one year after the initial pilot test.

6.0 PROJECT SCHEDULE

The following schedule is contingent upon approval of this pilot test work plan and completion of base support requirements.

Event	<u>Date</u>
Draft Pilot Test Work Plan to AFCEE MCB Camp Pendleton	July 6,1994
Approval to Proceed	August 25, 1994
Begin Initial Pilot Test	September 8, 1994
Interim Results Report	December, 1994
Respiration Test	February 1995
Final Respiration Test and Soil Sampling	October 1995

7.0 POINTS OF CONTACT

Mr. Tom DeCosta ACS Environmental Security Bldg 22165 Box 555008 Camp Pendleton, CA 92055-5008 (619) 725-9742

Mr. Patrick Haas AFCEE/ERT 8001 Arnold Dr. Brooks AFB, TX 78235-5325 (210)536-4314 FAX (210) 536-4330

Mr. Larry Dudus Parsons Engineering Science, Inc. 9404 Genesee Ave., Suite 140 La Jolla, CA 92037 (619) 453-9650 FAX (619) 453-9652 Mr. Doug Downey Parsons Engineering Science, Inc. 1700 Broadway, Suite 900 Denver, CO 80290 (303) 831-8100 FAX (303) 831-8208

8.0 REFERENCES

- Engineering-Science, Inc., 1992. Field Sampling Plan for AFCEE Bioventing, Denver, Colorado.
- Hinchee, R.E., Ong, S.K., Miller, R.N., Downey, D.C., Frandt, R., January 1992. Test Plan and Technical Protocol for a Field Treatability Test for Bioventing.
- Jacobs Engineering, IT Corp. CH2M Hill, April 1993. MCB Camp Pendleton, California underground storage tank draft site assessment report.

CONTENTS

PART II

DRAFT BIOVENTING PILOT TEST INTERIM TEST RESULTS REPORT SITE 13115 HEATING OIL UST MARINE CORPS BASE CAMP PENDLETON, CALIFORNIA

			Page
1.0	INTR	ODUCTION	II-1
2.0	SITE	13115 HEATING OIL UST	II-1
2.1	Pilot '	Test Design and Construction	II-1
	2.1.1	Air Injection Vent Well	II-1
	2.1.2	Monitoring Points	II-6
	2.1.3	Blower Unit	II-6
2.2	Soil a	nd Soil Gas Sampling Results	II-10
		Soil Sampling Results	II-10
	2.2.2	Soil Gas Sampling Results	II-10
2.3	Pilot '	Test Results	II-12
	2.3.1	Exceptions to Test Protocol Procedures	II-12
	2.3.2	Initial Soil Gas Chemistry	II-12
	2.3.3	In-Situ Respiration Rates	II-12
	2.3.4	Air Permeability	II-18
	2.3.5	Oxygen Influence	II-20
	2.3.6	Potential Air Emissions	II-20
2.4	Recor	mmendations	II-21
3.0	REFE	CRENCES	II-22
APPEN	DIX A	O&M MANUAL	
APPEN	DIX B	GEOLOGIC BORING LOGS AND CHAIN-OF-CUSTODY FORMS	

CONTENTS

PART II DRAFT BIOVENTING PILOT TEST INTERIM TEST RESULTS REPORT SITE 13115 HEATING OIL UST MARINE CORPS BASE CAMP PENDLETON, CALIFORNIA

			Page
1.0	INTR	CODUCTION	II-1
2.0	SITE	13115 HEATING OIL UST	II-1
2.1	Pilot'	Test Design and Construction	II-1
	2.1.1	Air Injection Vent Well	II-1
	2.1.2	Monitoring Points	II-6
	2.1.3	Blower Unit	II-6
2.2	Soil a	nd Soil Gas Sampling Results	II-10
		Soil Sampling Results	II-10
	2.2.2	Soil Gas Sampling Results	II-10
2.3	Pilot '	Test Results	II-12
	2.3.1	Exceptions to Test Protocol Procedures	II-12
		Initial Soil Gas Chemistry	II-12
	2.3.3	In-Situ Respiration Rates	II-13
	2.3.4	Air Permeability	II-14
	2.3.5	Oxygen Influence	II-14
	2.3.6	Potential Air Emissions	II-20
2.4	Recor	mmendations	II-22
3.0	REFE	ERENCES	II-23
APPEN	DIX A	O&M MANUAL	
APPEN	DIX B	GEOLOGIC BORING LOGS AND CHAIN-OF-CUSTODY FORMS	

FIGURES

Figure	Description	Page
2.1	Record Drawing, Vent Well/Vapor Monitoring Point Locations, Site 13115 Heating Oil UST	II-2
2.2	Geologic Cross Section A-A, Site 13115 Heating Oil UST	II-3
2.3	Record Drawing, Deep Air Injection Vent Well - VW1 Construction Details, Site 13115 Heating Oil UST	II-4
2.4	Record Drawing, Shallow Air Injection Vent Well - VW2 Construction Details, Site 13115 Heating Oil UST	II-5
2.5	Record Drawing Blower and Piping System Diagram, Site 13115 Heating Oil UST	II-7
2.6	Record Drawing, Monitoring Point Construction Details, Site 13115 Heating Oil UST	II-8
2.7	Blower System Instrumentation Diagram for Air Injection, Site 13115 Heating Oil UST	II-9
2.8	Respiration Test CP1-VW1, Site 13115 Heating Oil UST	II-15
2.9	Respiration Test CP1-VW2, Site 13115 Heating Oil UST	II-16
2.10	Respiration Test CP1-MPA-16, Site 13115 Heating Oil UST	II-17
2.11	Respiration Test CP1-MPA-23, Site 13115 Heating Oil UST	II-18
2.12	Respiration Test CP1-MPA-30, Site 13115 Heating Oil UST	II-19

TABLES

Table	Description	Page
2.1	Soil and Soil Gas Laboratory Analytical Results, Site 13115 Heating Oil UST	II-11
2.2	Initial Soil Gas Chemistry, Site 13115 Heating Oil UST	II-13
2.3	Oxygen Utilization Rates, Site 13115 Heating Oil UST	II-20
2.4	Pressure Response (inches of water) During Air Permeability, Site 13115 Heating Oil UST	II-21
2.5	Influence of Air Injection Vent Well on Monitoring Point Oxygen Levels. Site 13115 Heating Oil UST	II-22

PART II

DRAFT

BIOVENTING PILOT TEST INTERIM RESULTS REPORT SITE 13115 HEATING OIL UST MARINE CORPS BASE CAMP PENDLETON, CALIFORNIA

1.0 INTRODUCTION

The purpose of this Part II report is to describe the results of the initial pilot test at Building 13115 and to make specific recommendations for extended testing which will determine the long-term impact of bioventing on site contamination. A description of the site history and contaminants detected during previous investigations is described in Part I, the Bioventing Pilot Test Work Plan.

2.0 SITE 13115 HEATING OIL UST

At the time the Bioventing Pilot Test Work Plan was written, the leaking heating oil UST at Building 13115 was still in service. The UST has since been emptied, locked, and is no longer in service. Fuel for the boiler is currently being supplied by an aboveground tank located north of the boiler room.


2.1 Pilot Test Design and Construction


Installation of two air injection vent wells (VW1 and VW2) and four vapor monitoring points (MPs) at Building 13115 (designated CP1) was completed on September 9, 1994. Drilling services were provided by California Pacific Drilling of Moreno Valley, California. Well installation and soil sampling were directed by Parsons Engineering Science, Inc. (Parsons ES) geologists Mr. Larry Dudus and Mr. Christer Loftenius. The following sections describe the design and installation of the bioventing pilot test system at this site.


Two VWs (CP1-VW1 and CP1-VW2), four MPs (CP1-MPA, CP1-MPB, CP1-MPC, and CP1-MPBG) and a blower unit were installed at the site. Figures 2.1 and 2.2, respectively, depict the location of, and a geologic cross section for, the VWs and MPs completed at the site. The background MP (CP1-MPBG) was installed approximately 400 feet northeast of the site.


2.1.1 Air Injection Vent Well

An air injection vent well (CP1-VW1) was installed following procedures described in the Air Force Center for Environmental Excellence (AFCEE) bioventing protocol document (Hinchee et. al., 1992). Previous site characterizations detected the presence of a silt and clay layer from ground surface to approximately 15 feet below ground surface (bgs). To help insure adequate air flow through this silty clay layer, an additional well (CP1-VW2) was installed. Well CP1-VW2 is screened through the silty clay layer only. Figures 2.3 and 2.4 show construction details for CP1-VW1 and CP1-VW2, respectively.









The VWs were located as close to the center of contamination as possible without risking damage during UST removal which is planned in the near future. The VWs were constructed using 4-inch diameter Schedule 40 polyvinyl chloride (PVC) casings with 0.04-inch slotted PVC screen. The screen in CP1-VW1 was installed from 5.9 to 35.9 feet bgs. The screen in CP1-VW2 was installed from 4 to 14 feet bgs. The annular spaces between the well screen and borehole were filled with 4 x 12 silica sand. Bentonite pellets were placed above the sand and hydrated in place. The top of the wells were completed with flush-mounted metal well vaults set in concrete pads designed in accordance with San Diego County requirements.


The well casing tops were finished with 4-inch by 2-inch PVC T fittings. The fittings were attached to 2-inch diameter Schedule 40 PVC pipe. Inside the well vaults, PVC ball valves were installed in the 2-inch pipe just after the T fittings. Small-valved sampling ports were installed between the ball valves and each of the well heads. The 2-inch PVC pipe was installed underground and extends from the well heads to a valve box located next to the stairs behind Building 13115 (Figure 2.5). From the valve box, a single 2-inch PVC pipe continues above ground under the stairs and into the boiler room where the blower is housed. The PVC pipe is connected to a galvanized steel pipe at the blower with a rubber Fernco® connector.


2.1.2 Monitoring Points


Screens for CP1-MPA, CP1-MPB, and CP1-MPC were installed at 7, 16, 23, and 30 feet bgs. The MPs were located 14.6, 35.6, and 74.1 feet away from CP1-VW1, respectively. Screen intervals for the background MP were installed at 7, 13, 20, and 27 feet bgs. These intervals differed from the other three MPs to correspond closely with site lithology. The background MP was located approximately 300 feet northeast of CP1-VW1. The MPs were constructed as shown in Figures 2.2 and 2.6. Each MP monitoring interval was constructed using a 6-inch section of 1-inch diameter 0.02-inch slotted PVC well screen and a 0.25-inch diameter Schedule 80 PVC riser pipe extending to the ground surface. At the top of each riser, a ball valve and a 3/16-inch hose barb were installed. The top of each MP was completed with a flush-mounted metal well vault set in a concrete base. Thermocouples were installed at the 7- and 30-foot depths at CP1-MPA to measure soil temperature.

2.1.3 Blower Unit

A 1-horsepower Gast® regenerative blower unit was used for both the initial and the extended pilot tests. For the extended pilot test, the blower was installed in the boiler room located behind Building 13115. The fixed unit is plugged into a 120-volt outlet in the boiler room. The configuration, instrumentation, and specifications for this blower system are shown in Figure 2.7. The blower is currently injecting air at a total flow rate of approximately 20 standard cubic feet per minute (scfm) into CP1-VW1 and approximately 5 scfm into CP1-VW2 for the extended pilot test. After blower installation and start-up, Parsons ES engineers provided an operation and maintenance manual, equipment specifications, and monitoring forms, to base personnel. A copy of the O&M manual is provided in Appendix A.







VRV VACUUM RELIEF VALVE GAST[®] AG

VACUUM RELIEF VALVE GAST® AG 258 SET TO RELEASE AT 30 IN H20 VACUUM

(VI) VACUUM GAUGE (-60 - 0 IN H20) GAST $^{\circledR}$ AJ 497

BLOWER GAST® 1HP R4110N -50

PRV PRESSURE RELIEF VALVE GAST[®] AG 258 SET TO RELEASE AT 40 IN H20 PRESSURE

FCV(G) FLOW CONTROL VALVE (GATE)

TI) TEMPERATURE GAUGE (0 - 250°F) ASHCROFT® 30E 160R 025

(PI) PRESSURE GAUGE (0 – 60 IN H20) GAST[®] AJ 496

FCV(B) FLOW CONTROL VALVE (BALL)

PARSONS ENGINEERING SCIENCE, INC.

OFFICES IN PRINCIPAL CITIES

PARSONS

9404 GENESEE AVENUE • SUITE 140 LA JOLLA, CA 92037 • (619) 453-9650

	DESIGNED BY:
	LD
	DRAWN BY:
ĺ	MSB
١	DATE:
i	12/14/94

FIGURE 2.7 BLOWER SYSTEM INSTRUMENTATION DIAGRAM FOR AIR INJECTION SITE 13115 — HEATING OIL UST MCB CAMP PENDLETON, CALIFORNIA

2.2 Soil and Soil Gas Sampling Results

2.2.1 Soil Sampling Results

Sediments encountered beneath the site range from clays to fine gravels (Figure 2.2). Sediments encountered between the ground surface and 15 feet bgs consist of finer sediments ranging from clays to silty sands. A clay layer, up to 7 feet thick is found near the UST. This clay layer pinches out to the south near boring B13115-6. A silt layer, approximately 5 feet thick, is found between 10 to 15 feet bgs. The most abundant sediment type encountered beneath the site is well to poorly graded sands. The sands were encountered approximately 15 feet below the ground surface (bgs) down to a depth of 40 feet bgs. Up to 10-foot-thick lenses of silty sand and silt occur within the sands. Between 30 and 35 feet bgs the sand is underlain by a layer of sand and gravel approximately 5 feet thick. No ground water was encountered at the site.

Soil samples for laboratory analysis were collected at CP1-VW1-20, CP1-VW2-10 and CP1-MPA-30 using 18-inch split-spoon samplers with 2-inch diameter brass liners. Soil samples were shipped via Federal Express® to Pace laboratory in Huntington Beach, California, for chemical and physical analysis. Soil samples were analyzed for Total Recoverable Petroleum Hydrocarbons (TRPH) by EPA 418.1; Benzene, Toluene, Ethylbenzene and Xylenes (BTEX) by EPA 8020; iron; alkalinity; phosphates; pH; Total Kjeldahl Nitrogen (TKN); moisture content; and grain-size distribution. The results of these analyses are provided on Table 2.1. Chain-of-custody forms are provided in Appendix B.

Field evidence of hydrocarbon contamination was encountered from about 5 feet bgs to 35 feet bgs in CP1-VW1 and from 5 feet bgs to 16 feet bgs, the total depth of CP1-VW2. Both borings are located approximately 5 feet from the UST. Soils at these depths had moderate to strong hydrocarbon odors and had GasTech® hydrocarbon analyzer head space readings of up to 200 ppmv. However, no signs of soil staining or discoloration were observed. Soil from CP1-MPA had weak to moderate hydrocarbon odors from about 6 to 30 feet bgs. There was no field evidence of contamination in CP1-MPB or CP1-MPC. Analytical results ranged from 27.1 mg/kg for TRPH and non-detect for BTEX in CP1-VW2-10 to 9260 mg/kg for TRPH and non-detect, 1300 mg/kg, 160 mg/kg and 1400 mg/kg for BTEX, respectively, in CP1-VW1-20.

2.2.2 Soil Gas Sampling Results

Soil gas samples were collected from CP1-VW1, CP1-MPA-30, CP1-MPC-30 using 3-liter Tedlar® bags and a vacuum chamber. After the samples were collected in the Tedlar® bags, they were transferred to 1-liter SUMMA® canisters and shipped to the laboratory.

Soil gas samples were shipped via Federal Express® to Air Toxics, Inc., in Folsom, California for analysis by EPA TO-3 for Total Volatile Hydrocarbons (TVH) and BTEX. The TVH analyses were referenced to jet fuel (Molecular Weight = 156) as there is no suitable analysis for the volatile fraction of heating oil. The results of these analyses are provided on Table 2.1. Chain-of-custody forms are

Table 2.1 Soil and Soil Gas Laboratory Analytical Results Site 13115 Heating Oil UST Marine Corps Base Camp Pendleton, California

Analyte (Units) ^a			ocation - Depth Ground Surface)	
Soil Gas Hydrocarbons	CP1-VW1	CP1-MPA-30	CP1-MPC-30	
TVH ^b (ppmv)	360	860	170	
Benzene (ppmv)	0.28	0.74	ND(0.003)	
Toluene (ppmv)	0.99	2.5	0.066	
Ethylbenzene (ppmv)	1.7	1.9	0.047	
Xylenes (ppmv)	3.6	6.5	0.14	
Soil Hydrocarbons	CP1-VW1-20	CP1-VW2-10	CP1-MPA-30	CP1-MPBG
TRPH ^c (mg/kg)	9260	27.1	893	
Benzene (mg/kg)	ND (0.058)	ND (0.059)	ND (0.050)	
Toluene (mg/kg)	1.300	ND (0.059)	ND(0.050)	
Ethylbenzene (mg/kg)	0.160	ND(0.059)	ND (0.050)	
Xylenes (mg/kg)	1.400	ND (0.120)	ND (0.100)	
Soil Inorganics		•		
Iron (mg/kg)	906	7280	1880	
Alkalinity (mg/kg as Ca CO ₃ d)	150	80	120	
pH (Units)	8.75	7.59	6.77	
TKN ^e (mg/kg)	ND(40)	ND(40)	180	ND (40)
Phosphates (mg/kg)	33	71	33	
Soil Physical Parameters	3			
Moisture (% by wt)	14.7	17.0	0	
Gravel (%)	0.1	0.0	6.8	
Sand $(\%)$	85.7	41.5	77.2	
Silt (%)	10.9	37.1	11.2	
Clay (%)	3.4	21.4	4.8	

a ppmv = parts per million by volume; mg/kg = milligrams per kilogram.
b TVH = Total Volatile Hydrocarbons by TO-3.
c TRPH = Total Recoverable Petroleum Hydrocarbons by EPA 418.1.

ND = Not Detected. Detection limits are in parentheses.

d Ca Co₃ = Calcium Carbonate.

e TKN = Total Kjeldahl Nitrogen.

^{-- =} Not Analyzed.

provided in Appendix B. TVH concentrations ranged from 170 ppmv in CP1-MPC-30 to 860 ppmv at CP1-MPA-30. Benzene, Toluene, Ethylbenzene, and Total Xylenes concentrations ranged from non-detect, 0.066 ppmv, 0.047 ppmv, and 0.14 ppmv, respectively, in CP1-MPC-30 to 0.74 ppmv, 2.5 ppmv, 1.9 ppmv and 6.5 ppmv, respectively, in CP1-MPA-30.

2.3 Pilot Test Results

2.3.1 Exceptions to Test Protocol Procedures

Procedures described in the protocol document and the site-specific work plan (Part I) were used to complete the pilot test at this site. An exception to the protocol document included the addition of a second VW as previously described. Exceptions to the Part I work plan included adjusting the depths of the MP screened interval in accordance with lithologies and contamination distribution encountered during drilling.

2.3.2 Initial Soil Gas Chemistry

Prior to initiating air injection for the respiration test, the VWs and MPs were purged, and initial oxygen, carbon dioxide, and TVH concentrations were measured using portable gas analyzers, as described in the protocol document.

Table 2.2 summarizes the initial soil gas chemistry at the site. The results strongly indicate that biological fuel degradation has depleted the oxygen supply in the vadose zone near the UST. The zone of depleted oxygen extends from the Heating Oil UST to the soil south of CP1-MPA. Thirty feet from the UST, at CP1-MPB-30, oxygen concentration is still relatively low at 2.2 percent. Oxygen concentrations in the 7-, 16-, and 23-foot depths at CP1-MPB and throughout CP1-MPC were between 10 and 16.5 percent. Carbon dioxide was present at elevated concentrations ranging from 2.5 to 13 percent throughout the site. Carbon dioxide is a by-product of fuel biodegradation.

Despite location about 5 feet from the UST and the presence of hydrocarbon odor during drilling, initial oxygen concentration in CP1-VW2 was relatively high at 17.5 percent. This relatively high oxygen concentration (compared to CP1-VW1) could be due to the top of the well screen being less than 4 feet bgs and in contact with near-surface soil gas with high oxygen concentration. An undetected leak at the well head may also be contributing to the high oxygen concentration.

A background MP (CP1-MPBG) was installed approximately 400 feet northeast of the site. Oxygen concentrations in the background MP ranged from 15.5 to 19.1 percent. Carbon dioxide concentrations ranged from 1.6 to 5.0 percent. The 13-and 20-foot zones of CP1-MPBG had oxygen concentrations below 18 percent; therefore, an *in situ* respiration test was conducted in these two background MPs according to protocol document guidelines. The test was conducted to determine if oxygen uptake is due to factors other than fuel biodegradation.

Table 2.2

Initial Soil Gas Chemistry
Site 13115 Heating Oil UST

Marine Corps Base Camp Pendleton, California

Sample Location	Depth (ft bgs)	O ₂ (percent)	CO ₂ (percent)	TVH-Field (ppmv) ^a	TVH-Lab (ppmv) ^b	Temperature (°F)
CP1-VW1	5.9-35.9	2.6	12.0	1,900	360	
CP1-VW2	3.75-14	17.5	2.5	44		
CP1-MPA-7¢	7					72.6
CP1-MPA-16	16	0.0	12.0	1,200		
CP1-MPA-23	23	0.0	13.0	2,600	**	••
CP1-MPA-30	30	0.0	13.0	8,000	860	68.6
CP1-MPB-7	7	12.8	7.0	130		
CP1-MPB-16	16	10.0	7.5	56		
CP1-MPB-23	23	11.2	6.5	120		
CP1-MPB-30	30	2.2	10.5	160		
CP1-MPC-7	7	16.5	2.8	100		
CP1-MPC-16	16	10.0	7.2	100		
CP1-MPC-23d	· 23					
CP1-MPC-30	30	10.0	6.3	180	170	
CP1-MPBG-7	7	19.1	1.6	140		
CP1-MPBG-13	13	16.8	4.2	80		
CP1-MPBG-20	20	15.5	5.0	80		
CP1-MPBG-27d	27					

a Total volatile hydrocarbon field screening results.

2.3.3 In Situ Respiration Rates

An in situ respiration test was conducted at the site according to protocol document procedures. Air was injected into CP1-MPA-16, CP1-MPA-23, CP1-MPA-30, and CP1-VW1 for 20 hours using 1-scfm air pumps. Due to the temporary presence of water from bentonite hydration during probe installation, a respiration test was not conducted in CP1-MPA-7. A dilution chamber was used to inject helium into the MPs at a concentration between 3 and 4 percent.

During the air injection period, oxygen concentrations in CP1-VW1, CP1-VW2, CP1-MPA-16, CP1-MPA-23, and CP1-MPA-30 were increased to at least 19.0 percent. After air injection ceased, changes in soil gas composition were monitored over time. Oxygen, carbon dioxide, TVH, and helium were measured over a period of approximately 187 hours following the air injection period. The observed rates of

b Laboratory results referenced to Jet Fuel (Molecular Weight = 156)

No sample due to water in probe.

d No sample due to tight formation.

^{-- =} Not Analyzed

oxygen utilization were then used to estimate the aerobic fuel degradation rates at the site using procedures outlined in Section 5.7 of the protocol document. Figures 2.8 through 2.12 present the results of *in situ* respiration testing at the site, and Table 2.3 provides a summary of the observed oxygen utilization rates. The oxygen utilization rates observed in contaminated soils were very consistent and ranged from 0.019 percent per hour (%/hr) to 0.023 %/hr. Helium levels remained relatively constant when compared to oxygen utilization, indicating that MP leaks or diffusion were not contributing to oxygen loss.

A respiration test was also conducted in background points CP1-MPBG-13 and CP1-MPBG-20. Oxygen concentrations were increased to 20.5 percent by air injection as described above. The points were monitored for approximately 7 days. During this time, oxygen concentrations in CP1-MPBG-13 and CP1-MPBG-20 decreased 1 and 1.3 percent, respectively. Due to this very low rate of background oxygen utilization, respiration rates observed in CP1-VW1 and CP1-MPA are attributed to biological breakdown of petroleum hydrocarbons and not inorganic or natural carbon sources.

An estimated 40 to 170 milligrams (mg) of fuel per kilogram (kg) of soil can be biodegraded each year. The fuel consumption rates were calculated using the observed oxygen utilization rate in CP1-VW1, CP1-VW2, CP1-MPA-16, CP1-MPA-23, and CP1-MPA-30, estimated air-filled porosities of 0.213 and 0.05 liters of air/kg of soil for silty clay and sandy soils, respectively, and a conservative ratio of 3.5 mg of oxygen consumed for every 1 mg of fuel biodegraded.


2.3.4 Air Permeability


An air permeability test was conducted at the site according to protocol document procedures. During the test, the majority of the air flow was through the pressure relief valve. With the pressure relief valve set at 30 inches of water, the flow rate was measured at approximately 4 scfm. Air was injected into CP1-VW1 for approximately 20 hours at a rate of approximately 4 scfm. The pressure responses at CP1-VW2 and each MP are listed on Table 2.4. The pressure measured at most MPs continued to rise slightly for the first 3 hours. A minimum radius of pressure influence of 74.1 feet was observed at all depths in CP1-MBC except for 7 feet bgs. There was no observed pressure increase at 7 feet bgs in CP1-MPB or CP1-MPC, however, a slight pressure increase was observed in CP1-MPA-7, 14.6 feet from CP1-VW1.


The dynamic method of determining air permeability, as detailed in the protocol document, was used to calculate air permeability. Permeability values ranged from 5 to 12 darcys. However, these calculated permeabilities seem high compared to the physical appearance of soil samples. Lower permeability readings were associated with the tighter soils observed above 15 feet bgs and in a silt lens at CP1-MPA-30.

2.3.5 Oxygen Influence

The depth and radius of oxygen influence in the subsurface, resulting from air injection into the central VW during pilot testing, is the primary design parameter for full-scale bioventing systems. Optimization of full-scale and multiple VW systems requires pilot testing to determine the volume of soil that can be oxygenated at a given flow rate and VW screen configuration.







PARSONS ENGINEERING SCIENCE, INC.

OFFICES IN PRINCIPAL CITIES


PARSONS

9404 GENESEE AVENUE · SUITE 140
LA JOLLA, CA 92037 · (619) 453-9650

DESIGNED BY:
LD
DRAWN BY:
MSB
DATE:
12/14/94

DESIGNED BY:
LD
DRAWN BY:
MSB
DATE:
12/14/94

MCB CAMP PENDLETON, CALIFORNIA



PARSONS ENGINEERING SCIENCE, INC.

OFFICES IN PRINCIPAL CITIES

PARSONS

9404 GENESEE AVENUE • SUITE 140 LA JOLLA, CA 92037 • (619) 453-9650 DESIGNED BY:

LD

DRAWN BY:

MSB

DATE:

12/14/94


FIGURE 2.10

RECORD DRAWING RESPIRATION TEST

CPI-MPA-16

SITE 13115 - HEATING OIL LIST

SITE 13115 — HEATING OIL UST MCB CAMP PENDLETON, CALIFORNIA



PARSONS ENGINEERING SCIENCE, INC.

OFFICES IN PRINCIPAL CITIES

9404 GENESEE AVENUE • SUITE 140
LA JOLLA, CA 92037 • (619) 453-9650

DESIGNED BY:

LD

DRAWN BY:

MSB

DATE:


12/14/94

FIGURE 2.11

RECORD DRAWING RESPIRATION TEST

CPI-MPA-23

SITE 13115 - HEATING OIL UST MCB CAMP PENDLETON, CALIFORNIA



PARSONS ENGINEERING SCIENCE, INC.

OFFICES IN PRINCIPAL CITIES

PARSONS

9404 GENESEE AVENUE • SUITE 140 LA JOLLA, CA 92037 • (619) 453-9650 DESIGNED BY:

LD

DRAWN BY:

MSB

DATE:
12/14/94

FIGURE 2.12
RECORD DRAWING RESPIRATION TEST
CPI-MPA-30

SITE 13115 — HEATING OIL UST MCB CAMP PENDLETON, CALIFORNIA

Table 2.3

Oxygen Utilization Rates Site 13115 Heating Oil UST Marine Corps Base Camp Pendleton, California

Location	O ₂ Loss ^a (percent)	Test Duration (hr)	O ₂ Utilization ^a Rate (percent/hr)	Hydrocarbon Degradation Rate (mg/kg/yr)
CP1-VW-1	4.0	186	0.021	40
CP1-VW-2	4.0	186	0.023	170
CP1-MPA-16	3.8	186	0.019	30
CP1-MPA-23	4.0	186	0.022	40
CP1-MPA-30	3.2	186	0.021	140

^a Value based on linear regression.

Table 2.5 describes the change in soil gas oxygen levels that occurred after 30 days of air injection at the site. This air injection period at 4 scfm produced increases in soil gas oxygen levels at a distance of at least 35.6 feet from the central VW at all depths in CP1-MPB. Oxygen concentration at CP1-MPC, 74.1 feet from CP1-VW1, increased slightly at 7 feet bgs, but decreased slightly at 16 and 30 feet bgs. This decrease is most likely a result of soil gas with lower oxygen concentration being displaced outward as air is being injected into CP1-VW1.

The zone of oxygen influence appears to be beyond the known limit of contamination in the sandier soils below 15 feet bgs. The zone of oxygen influence in the silty clay above 15 feet bgs is less certain. CP1-MPA-7 could not be sampled due to residual probe construction water. CP1-MPB-7 and CP1-MPC-7 had oxygen increases of 1 percent after 30 days of air injection. This slight increase is within the limit of field equipment error. Therefore, to insure adequate oxygenation of sandy and clayey zones, the flow control valves to CP1-VW2 were opened slightly. Currently, air is being injected into CP1-VW1 and CP1-VW2 at approximately 4 scfm and 2 scfm respectively. These flow rates and the tendency of oxygen-rich soil gas to diffuse into areas of oxygen-deficient soil gas, even in clay-rich zones, should provide sufficient oxygen to all heating oil related contaminated soil at the site.

2.3.6 Potential Air Emissions

Site contamination consists of heating oil fuel, a compound of relatively low volatility. Soil samples had maximum field head space readings of 200 ppmv. The maximum TVH concentration determined by laboratory analysis was 860 ppmv. Maximum BTEX concentrations of 0.74, 2.5, 1.9, and 6.5 ppmv, respectively, were detected. The long-term potential for air emissions from full scale bioventing operations at this site is low. Initial emissions should be minimal because accumulated vapors will move slowly outward from the air injection point and will

Table 2.4

Pressure Response (inches of water) During Air Permeability Test
Site 13115 Heating Oil UST
Marine Corps Base Camp Pendleton, California

Elapsed Time	CP-VV	V2	CP1	Lo MPA-1		and Deptl		ogs) -MPB	1		CP1	-MPC	•
(Minutes)	<u> </u>	7	16	23	30	7	16	23	30	7	16	23	30
0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
1	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
2	0.0	0.05	0.1	0.1	0.1	0.0	0.0	0.0	0.05	0.0	0.1	0.0	0.1
3	0.1	0.05	0.2	0.2	0.3	0.0	0.0	0.0	0.0	0.0	0.1	0.0	0.1
4	0.1	0.05	0.2	0.3	0.3	0.0	0.0	0.0	0.0	0.0	0.1	0.0	0.0
5	0.1	0.05	0.2	0.3	0.4	0.0	0.0	0.0	0.05	0.0	0.1	0.0	0.0
6	0.1	0.05	0.2	0.3	0.4	0.0	0.0	0.0	0.0	0.0	0.1	0.0	0.0
7	0.1	0.05	0.2	0.4	0.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
8	0.1	0.05	0.2	0.4	0.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
9	0.1	0.05	0.3	0.4	0.5	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
10	0.1	0.05	0.3	0.4	0.6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
12	0.1	0.05	0.3	0.4	0.6	0.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
14	0.1	0.05	0.3	0.4	0.6	0.0	0.0	0.0	0.0	0.0	0.1	0.0	0.0
16	0.1	0.05	0.3	0.4	0.6	0.0	0.05	0.1	0.05	0.0	0.1	0.0	0.0
18	0.1	0.05	0.4	0.5	0.7	0.0	0.1	0.2	0.2	0.0	0.1	0.0	0.05
20	0.1	0.05	0.4	0.5	0.7	0.0	0.1	0.2	0.2	0.0	0.1	0.0	0.05
22	0.1	0.05	0.4	0.5	0.8	0.0	0.2	0.2	0.2	0.0	0.2	0.0	0.05
24	0.1	0.05	0.3	0.5	0.8	0.0	0.2	0.2	0.3	0.0	0.1	0.1	0.1
26	0.1	0.05	0.4	0.6	0.9	0.0	0.2	0.3	0.3	0.0	0.2	0.2	0.1
28	0.1	0.05	0.4	0.6	0.9	0.0	0.3	0.3	0.4	0.0	0.2	0.3	0.1
30	0.1	0.05	0.4	0.6	0.9	0.0	0.3	0.3	0.4	0.0	0.2	0.4	0.1
33	0.1	0.05	0.4	0.6	0.9	0.0	0.3	0.3	0.5	0.0	0.1	0.5	0.1
36	0.1	0.05	0.5	0.6	1.0	0.0	0.2	0.2	0.3	0.0	0.15	0.7	0.05
39	0.1	0.05	0.5	0.7	1.0	0.0	0.2	0.2	0.3	0.0	0.15	0.75	0.1
42	0.1	0.05	0.5	0.7	1.0	0.0	0.2	0.25	0.3	0.0	0.15	0.75	0.1
45	0.1	0.05	0.5	0.7	1.0	0.0	0.05	0.2	0.3	0.0	0.15	0.95	0.1
48	0.1	0.05	0.5	0.7	1.0	0.05	0.2	0.25	0.35	0.0	0.2	1.1	0.15
51	0.1	0.05	0.5	0.75	1.1	0.0	0.25	0.25	0.35	0.0	0.2	1.1	0.15
54	0.1	0.05	0.5	0.75	1.1	0.0	0.2	0.25	0.35	0.0	0.15	1.05	0.10
. 57	0.1	0.05	0.5	0.75	1.1	0.0	0.2	0.25	0.35	0.0	0.15	0.5	0.15
60*	0.1	0.05	0.5	0.75	1.1	0.0	0.25	0.25	0.35	0.0	0.20	0.0	0.15
75	0.1	0.05	0.4	0.7	0.9	0.0	0.3	0.35	0.45	0.0	0.25	0.0	0.15
90	0.2	0.05	0.4	0.8	1.3	0.05	0.25	0.35	0.45	0.0	0.15	0.0	0.1
105	0.2	0.05	0.4	0.8	1.4	0.05	0.2	0.25	0.4	0.0	0.15	0.0	0.1
120	0.2	0.0	0.4	0.8	1.4	0.05	0.25	0.3	0.45	0.0	0.15	0.0	0.05
150	0.2	0.4	0.5	0.9	1.5	0.05	0.25	0.35	0.50	0.0	0.20	0.4	0.15
180	0.2	0.9	0.5	0.9	1.5	0.05	0.27	0.35	0.5	0.0	0.15	0.55	0.15
240	0.2	0.05	0.45	0.9	1.5	0.05	0.25	0.35	0.5	0.0	0.15	<0	0.15
480	0.05	0.05	0.2	0.45	1.2	0.0	0.0	0.05	0.15	<0	<0	<0	<0
1200	0.05	0.05	0.2	0.60	1.2	0.0	0.0	0.05	0.15	<0	<0	1.6	<0

^{*} Collected soil gas samples.

Table 2.5

Influence of Air Injection Vent Well on Monitoring Point Oxygen Levels
Site 13115 Heating Oil UST
Marine Corps Base Camp Pendleton, California

Sample Location	Distance from VW1 (ft)	Depth (ft. bgs)	Initial O2 ^a (percent)	Final O2 ^b (percent)
CP1-VW-2	9.6	3.75-16	17.5	16.0
CP1-MPA-16	14.6	16	0.0	20.1
CP1-MPA-23	14.6	23	0.0	20.0
CP1-MPA-30	14.6	30	0.0	20.5
CP1-MPB-7	35.6	7	12.8	13.8
CP1-MPB-16	35.6	16	10.0	17.5
CP1-MPB-23	35.6	23	11.2	12.0
CP1-MPB-30	35.6	30	2.2	18.2
CP1-MPC-7	74.1	7	16.5	17.6
CP1-MPC-16	74.1	16	10.0	8.8
CP1-MPC-30	74.1	30	10.0	6.2

a Initial site readings.

be biodegraded as they move horizontally through the soil. During the air permeability test, air was injected at 4 scfm. Health and safety hydrocarbon-analyzer air monitoring of the breathing zone at the site indicated that total hydrocarbon concentrations did not increase above 1 ppmv during the initial days of the test. The initial day of bioventing generally produces the highest potential for emissions as the first pore volume of soil gas is replaced.

2.4 Recommendations

Field observations and analytical results tend to indicate the extent of contamination has been greatly over estimated. Figures from previous reports show heating oil contamination extending to the southern end of the building, approximately 80 feet from the UST. However, previous site investigation borings appear to be closer to the UST than indicated on investigation report figures. Location of VWs and MPs were based on these figures. As a result, it appears that CP1-MPB and CP1-MPC are outside the zone of contamination. At a distance from the UST of approximately 10 feet, CP1-MPA maybe on the edge of the contaminated soil.

Initial bioventing tests at this site indicate that oxygen had been depleted in the contaminated soils, and that air injection is an effective method of stimulating aerobic fuel biodegradation. However, the observed biodegradation rates were lower than expected. The lower than expected biodegradation may be due, in part, to the majority of MPs being located out of the zone of significant soil

b Readings after 31 days of air injection.

contamination. AFCEE has recommended that air injection continue at this site to determine the long-term radius of oxygen influence and the effects of time, available nutrients, and changing temperatures on fuel biodegradation rates.

AFCEE has also recommended the installation of another MP, closer to the UST, in a zone of greater contamination at 15 to 20 feet bgs. Additional soil samples will be collected and analyzed for TRPH, BTEX, moisture, nutrients and salinity. A respiration test will be conducted in this MP. Depending on the results of the sample analysis and the respiration test, the limited addition of moisture and/or nutrients (to the new MP only) will be considered as a means to increase the bioremediation rate.

A 1-horsepower regenerative blower has been installed at the site for continuous air injection. In February 1995, Parsons ES will return to the site to conduct a repeat respiration test. In October 1995, a final respiration test will be conducted, and soil and soil gas samples will be collected from the site to determine the degree of remediation achieved during the first year of *in situ* treatment.

3.0 REFERENCES

- Engineering-Science, Inc. 1992. Field Sampling Plan for AFCEE Bioventing. Denver, Colorado.
- Hinchee, R.E., Ong, S.K., Miller, R.N., Downey, D.C., Frandt, R., 1992. Test Plan and Technical Protocol for a Field Treatability Test for Bioventing, January.
- Jacobs Engineering, IT Corp. CH₂M Hill, April 1993. Marine Corps Base Camp Pendleton, California. Underground Storage Tank Draft Site Assessment Report.

APPENDIX A O&M MANUAL

REGENERATIVE BLOWER OPERATIONS AND MAINTENANCE MANUAL FOR EXTENDED TESTING SYSTEM AT MARINE CORPS BASE CAMP PENDLETON BUILDING 13115

Prepared for:

AIR FORCE CENTER FOR ENVIRONMENTAL EXCELLENCE BROOKS AFB, TEXAS AND ACS ENVIRONMENTAL SECURITY MCB CAMP PENDLETON, CALIFORNIA

USAF CONTRACT F33615-90-D-4014, DELIVERY ORDER 14

OCTOBER 1994

Prepared by:

PARSONS ENGINEERING SCIENCE, INC. 9404 Genesee Avenue, Suite 140 San Diego, California 92037

INTRODUCTION

This document has been prepared by Parsons Engineering Science, Inc., to support the bioventing initiative contract awarded by the Air Force Center for Environmental Excellence (AFCEE). The contract involves the conducting of bioventing pilot tests at approximately 135 sites on 38 Air Force Bases across the United States. As part of AFCEES program of technology transfer, several pilot tests are being conducted at military installations other than air force bases.

At most sites, bioventing systems will be installed upon completion of the bioventing pilot tests for the purpose of extended pilot testing. These systems will operate for a one year period to provide further information as to the feasibility of the technology at each site, and to provide interim remedial action.

The Operations and Maintenance Manual has been created for sites at which blowers have been installed for extended pilot testing. Basic maintenance of these systems is the responsibility of the base. The manual is to be used by base personnel to guide and assist them in operating and maintaining the blower system. Section 2 provides a synopsis of the blower system configuration. Section 3 of this document describes the blower. Section 4 details the maintenance requirements and provides maintenance schedules. Section 5 describes the system monitoring that is required to forecast system maintenance needs and provide data for the extended pilot test.

BLOWER SYSTEM CONFIGURATION SUMMARY

System Type	injection
Blower	regenerative
Blower Model	R4110N-50
Motor (Horsepower)	1.0
Knock-Out Chamber	none
Sampling Port	none
Inlet Temperature Gauge (range)	not applicable
Inlet Vacuum Gauge (range)	-60" - 0" H ₂ 0
Inlet Filter (part no.)	AJ134E
Outlet Temperature Gauge (range)	0°-250° F
Outlet Pressure Gauge (range)	0" - 60" H ₂ 0
Pressure/Vacuum Relief Valve Set @ (give unit of measure)	30" H ₂ 0

BIOVENTING SYSTEM OPERATION

3.1 PRINCIPLE OF OPERATION

Bioventing is the forced injection of fresh air, or withdrawal of soil gas, to enhance the supply of oxygen for *in situ* bioremediation. Either a pressure (air injection) or vacuum (vapor extraction) blower unit is used to inject or withdraw air into or from the soil, thereby supplying fresh air with 20.8 percent oxygen to the contaminated soils. Once oxygen is provided to the subsurface, existing bacteria will proceed with the breakdown of fuel residuals.

An injection blower system has been installed at MCB Camp Pendleton, Building 13115.

3.2 SYSTEM DESCRIPTION

3.2.1 Blower System

A Gast series R4 blower powered by a one horsepower direct-drive motor is the workhorse of this bioventing system. This blower is rated at a flow rate of 92 standard cubic feet per minute (scfm) at open flow; however, the actual performance of the blower will vary with changing site conditions. As installed at Building 13115, the blower was producing an estimated flow rate of 65 scfm at a pressure of 28 inches of water. It has been reduced to 30 scfm and should remain at this flow rate. The system includes an air filter to remove any particulates which are entrained in the air stream, and several valves and monitoring gauges which are described in the next section. A schematic of the blower system installed at Building 13115 is shown on the figure in Attachment A. Corresponding blower performance curves, and relevant service information are also provided.

3.2.2 Monitoring Gauges

The bioventing system is equipped with vacuum, pressure, and temperature gauges. Gauges have been installed on the air injection system at the following locations: a vacuum gauge in the inlet piping, a pressure and a temperature gauge in the outlet piping. The temperature gauge is used to monitor the outlet temperature to determine the change in temperature across the blower. Ambient air temperature can be estimated and used as the inlet temperature since an inlet temperature gauge is not present. See the figure in the attachment for the locations of the gauges installed on the blower system.

SYSTEM MAINTENANCE

Although the motor and blower are relatively maintenance free, periodic system maintenance is required for proper operation and long life. Recommended maintenance procedures and schedules are described in detail in the instruction manuals included in Attachments A and B and briefly summarized in this section.

Filter inspection must be performed with the system turned off. To re-start the motor, open the manual air dilution valve to protect the motor from excessive strain, start motor, and slowly close dilution valve.

4.1 BLOWER/MOTOR

The blower and motor are relatively maintenance free and should not require any periodic maintenance during the 1-year extended testing period. Both blower and motor have sealed bearings and do not require lubrication.

4.2 AIR FILTER

To avoid damage caused by passing solids through the blower, an air filter has been installed in-line before the blower. The filter element is paper and is accompanied by a polyurethane foam prefilter. The filter should be checked weekly for the first 2 months of operation. Again, a facility employee should determine the best schedule for filter replacement. The polyurethane prefilters can be washed with lukewarm water and a mild detergent. Paper filter elements should never be washed, but should be disposed of and replaced as necessary. When the inlet vacuum is above 25 inches of water, a dirty filter element should be suspected, and cleaning or replacement should be performed.

To remove the filter, loosen the wing nut, lift the metal top off the air filter, and lift the air filter from the metal housing. Remove the polyurethane prefilter (if applicable) and wash before replacing. When replacing the filter, be careful that the rubber seals remain in place.

The filter element is manufactured by Gast Manufacturing Corp. in Benton Harbor, Michigan. Their telephone number is (616) 926-6171. Additional filters can also be obtained through Parsons ES in La Jolla, California. The Parsons ES contact is Mr. Larry Dudus. He can be reached at (619) 453-9650. The filter model number is AJ126D, and the number for the replacement element is AJ134E. It is recommended that at least one spare air filter be kept at the site, four spare filters were supplied with the blower system.

4.3 MAINTENANCE SCHEDULE

The following maintenance schedule is recommended for this system. The filter should be checked once per month and washed or replaced as necessary (see Section 5.2). During the initial months of operation more frequent monitoring is recommended to ensure that any start-up problems are quickly corrected. A daily drive-by inspection is recommended during the initial 2 weeks of operation to ensure that the blower system is still operating with no unusual sounds. Data collection sheets that can be used to record maintenance activities are included in Attachment B.

4.4 TROUBLESHOOTING

<u>Symptoms</u>	Possible Diagnosis	Possible Remedy
Excess Vibration	Impeller damaged by	Replace impeller
	foreign material	Clean impeller, install
	Impeller contaminated by foreign material	adequate filtration
Abnormal Sound	Motor bearing failed	Replace bearings
	Impeller rubbing against	Repair blower, check
	cover or housing	clearances
Increase in Sound	Foreign material can coat	Replace foam muffler
	or destroy muffler foam	elements, trap or filter
		foreign material
Blown Fuse	Electrical wiring problem	Have qualified person
		check fuse capacity
		and wiring
Unit Very Hot	Running at too high a	Install or adjust relief
	pressure or vacuum	valves

4.5 MAJOR REPAIRS

Blowers systems are very reliable when properly maintained. Occasionally, a motor or blower will develop a serious problem. If a blower system fails to start, and a qualified electrician verifies that power is available at the blower, the Parsons ES Site Manager, Larry Dudus, should be called at (619) 453-9650. Parsons ES is responsible for major repairs during the first year of operation.

SYSTEM MONITORING

5.1 BLOWER PERFORMANCE MONITORING

To monitor the blower performance, vacuum, pressure, and temperature will be measured. These data should be recorded weekly on a data collection sheet (provided in Attachment B). All measurements should be taken at the same time while the system is running. Because the system is loud, hearing protection should be worn at all times.

5.1.1 Vacuum/Pressure

With hearing protection in place, open the boiler room door where the blower is housed and record all vacuum and pressure readings directly from the gauges (in inches of water or psi). Record the measurements on a data collection sheet (Attachment B).

5.1.2 Flow Rate

The flow rate through the vent well and soils can be calculated when the inlet vacuum and outlet pressure of the blower are known and if the flow through the air bleed valve is known. The pressure change across the blower (vacuum + pressure) can be compared to the performance curves for the blower in Attachment A to determine the approximate flow rate.

5.1.3 Temperature

With hearing protection in place, open the boiler room door where the blower is housed and record the temperature readings directly from the gauges in degrees Fahrenheit (°F). Record the measurements on a data collection sheet (provided in Attachment B). If required the temperature change can be converted to degrees Celsius (°C) using the formula $^{\circ}C = (^{\circ}F - 32) \times 5/9$.

5.3 MONITORING SCHEDULE

The following monitoring schedule is recommended for this system. During the initial months of operation, more frequent monitoring is recommended to ensure that any start up problems are quickly corrected. Data collection sheets have been provided to assist your data collection and are included in Attachment B.

Monitoring Item

Monitoring Frequency

Vacuum/Pressure

Once per week.


Temperature

Once per week.

Air Filter

Clean as needed.

ATTACHMENT A



LEGEND

INLET AIR FILTER GAST[®] AJ 126D

VRV VACUUM RELIEF VALVE GAST[®] AG 258 SET TO RELEASE AT 30 IN H20 VACUUM

(VI) VACUUM GAUGE (-60 - 0 IN H20) GAST $^{\circledR}$ AJ 497

BLOWER GAST® 1HP R4110N -50

PRV PRESSURE RELIEF VALVE GAST[®] AG 258 SET TO RELEASE AT 40 IN H20 PRESSURE FCV(G) FLOW CONTROL VALVE (GATE)

TI) TEMPERATURE GAUGE (0 - 250°F) ASHCROFT® 30E 160R 025

PI PRESSURE GAUGE (0 – 60 IN H20) GAST[®] AJ 496

FCV(B) FLOW CONTROL VALVE (BALL)

PARSONS ENGINEERING SCIENCE, INC.

OFFICES IN PRINCIPAL CITIES

PARSONS

9404 GENESEE AVENUE • SUITE 140 LA JOLLA, CA 92037 • (619) 453-9650

DESIGNED BY:
LD
DRAWN BY:
MSB
DATE:

BLOWER SYSTEM
INSTRUMENTATION DIAGRAM FOR AIR INJECTION
SITE 13115 — HEATING OIL UST
MCB CAMP PENDLETON, CALIFORNIA

ATTACHMENT B





Post Office Box 97 Benton Harbor, MI. 49023-0097

Ph: 616/926-6171 Fax: 616/925-8288

INSTALLATION AND OPERATING **INSTRUCTIONS** FOR GAST **HAZARDOUS DUTY REGENAIR BLOWERS**

This instruction applies to the following models ONLY: R3105N-50, R4110N-50, 4310P-50, R4P115N-50, R5125Q-50, 325R-50, R6130Q-50, R6P155Q-50.

Gast Authorized Service Facilities are Located in the locations listed below

Gast Manufacturing Corporation 505 Washington Avenue Carlstadt, N. J. 07072

Ph: 201/933-8484 Fax: 201/933-5545

13824 Bentley Place

Cerritos, CA. 90701

Ph: 310/404-2721

Ph: 800/843-5558

Fax: 310/404-7975

Brenner Fiedler & Associates Wainbee Limited 215 Brunswick Blvd. Pointe Claire, Quebec

Canada H9R 4R7 Ph: 514/697-8810 Fox: 514/-697-3070

2550 Meadowbrook Road Benton Harbor, MI. 49022 Ph: 616/926-6171 Fax: 616/925-8268

Gast Manufacturing Corporation

Wainbee Limited 5789 Coopers Ave. Mississauga, Ontario

Canada L42 356 Ph: 416 243-1900 Fax: 416:243-2336

Japan Machinery Central PO Box 1451 Toyko 100-91, Japan Ph: 813 3573-5421

Fax: 813 3571-7896

Gast Manufacturing Co. Ltd Halifax Road, Cressex Estate High Wycombe, Bucks HP12 3SN England

Ph: 44 494 523571 Fax: 44 494 436588

SERVICING


⚠ WARNING To retain their sealed construction they should be serviced by Gast authorized service centers ONLY. These models are sealed at the factory for very low leakage.

⚠ WARNING Turn off electric power before removing blower from service. Be sure rotating parts have stopped. Electric shock or severe cuts can result. Inlet and exhaust filters attached to the blower may need cleaning or replacement of the elements. Failure to do so will result in more pressure drop, reduced air flow and hotter opera-

tion of the blower. The outside of the unit requires cleaning of dust and dirt. The inside of the blower also may need cleaning to remove foreign material coating the impeller and housing. This should be done at a Gast Authorized Service Center. This buildup can cause vibration, failure of the motor to operate or reduced flow.


KEEP THIS INFORMATION WITH THIS BLOWER. REFER TO IT FOR SAFE INSTALLATION, OPERATION OR SERVICE.

MOTOR WIRING DIAGRAM FOR R4110N-50 & R3105N-50



MOTORS WIRING DIAGRAM FOR R4310P-50


TO REVERSE ROTATION. INTERCHANGE THE EXTERNAL CONNECTIONS TO ANY TWO LEADS.




>>* WARNING THIS MOTOR IS THERMALLY PROTECTED AND WILL AUTOMATICALLY RESTART WHEN PROTECTOR RESETS. ALWAYS DISCONNECT POWER SUPPLY BEFORE SERVICING.

MOTORS WIRING DIAGRAM FOR R5325R-50, R6350R-50, R6P355R-50, & R7100R-50

TO REVERSE ROTATION. INTERCHANGE THE EXTERNAL CONNECTIONS TO ANY TWO LEADS.






nness kegenerative Blowers, Notor Mounted to 92 cfm



REGENAIR® R4 Series





MODEL R4110-2 52" H₂O MAX. PRESSURE, 92 CFM OPEN FLOW

PRODUCT FEATURES

- Oilless operation
- TEFC motor mounted
- · Can be mounted in any plane
- Rugged construction/low maintenance
- Can be operated blanked-off

COMMON MOTOR OPTIONS

- 115/208-230V, 60 Hz; 110/220-240V, 50 Hz, single phase
- 208-230/460V, 60 Hz; 190-230/380-415V, 50 Hz, three phase
- 575V, 60 Hz, three phase

RECOMMENDED ACCESSORIES


- Pressure gauge AJ496
- Filter AG338
- Muffler AJ121D
- Relief valve AG258


Various brand name motors are used on any model at the discretion of Gast Mfg. Corp.

Important Notice:

Pictorial and dimensional data is subject to change without notice.

Product Dimensions Metric (mm) U.S. Imperial (inches)









Madelay						_					
Model Number	Motor Specs	Full Load Amps	НР	HP RPM		Max Pressure "H _r O mbar		Flow	Ne	t Wt.	
R4110-2	110/220-240-50-1	9.0/4.5-5.7	0.6	2850			cfm	m³h	lbs.	kg	
	115/208-230-60-1	9.8/5.2-4.9	1.0		38	95	74	126	44		
R4310A-2	190-220/380-415-50-3	2.6-3.3/1.3-1.4		3450	52	130	92	156	41	18,6	
1140104-2	208-230/460-60-3	3.4-3.2/1.6	0.6	2850	38	95	74	126			
1	37 100 00 0	0.4-5.2/1.0	1.0	3450	52	130	92	156	41	18,6	

Product Performance (Metric U.S. Imperial)

Black line on curve Is for 60 cycle performance.

Blue line on curve Is for 50 cycle performance.





Name	RI	R2	R3	R4	R5	R6	R6P	R6PP/R6PS	R7
pver ·	AIOIA	AJIOIB	AJIOIC	MIDID	AJIDIEQ	1411015	1.11221	•	
nut	BC187	BC187	BC181	BC181		AJIOIF	MIDIK	(2)AJ101KA	AJIDIG
pellor	AJ102A	AJ1028Q	AJ102C		BC181	BC181	BC181	(2)BC182	BC183
iquare Key	AH212C	AH212	AB136A	AJ102D	AJ102E	AJ102FR	AJ102K	(2)AJ102KA	AJ102GA
Shim Spacer (s)	AJ132	AE686-3	AJ109	AB136D	AB136	AB136	AB136	(2)AB136	AC628
aining Ring	AJ145	AJ145		Y1108	AJ109	AJII6A	AJ116A	AJ116A	AJ110
de ising	AJIOJA		AJ149	AJ149					
Autilier Box	V3103V	AJ103BQ	AJ103C	AJ103DR	AJ103E	AJ103F	AJ103K	AJ103KD	AJ103GA
pring					AJ104E	AJ104F		, = , 00 (0	MIMBA
Agoam	(4) 4 (1) 20 (AJ113DR	AJ113DQ	AJ113FQ	AJ113FQ		AJII3G
Boam	(4)AJ112A	(4)AJ112B	(4)AJ112C	(4)AJ112DS	(4)AJ112ER	(6)AJ112F	(8) AJ112K		
		(Z)AJ112BQ	(2) AJ112CQ	(2)AJ112DR	(2)AJ112EQ		1		(8)AJ112GA
Muttler Extensio Adapter Plate		AJ106BQ K396	A1106CQ	AJ106DQ		AJ106FQ	AJ104K		AJI04GA
		, , , , , , , , , , , , , , , , , , ,							K395

MOTOR CHART

ESENAIR	Valorio		***	
ODEL	MOTOR	MOTOR SPECIFIC	CATIONS	
UMBER	MOTOR	60 HZ	50 HZ	
DEK	NUMBER	VOLTS	SIJOV	PHASE
102		******	**************************************	**************************************
102C	JIIIX		110/220-240	1
2 3	J112X	115	00000000000000000000000000000000000000	1
-	1311X	115/208-230	110/220	ī
303A	J411X	115/208-230	110/220	1
303F	1310		220/380-415	3."
T6-1/R3105-12	J313	208-230	220	3
		115/208-230	110/220-240	1
3 A-1/R3305A- 110-2		208-230/460		3
310A-2	J611AX		110/220-240	1,
	J610	208-230/460	220/380-415	3
3z5A-2	XITSL	115/208-230		1
125-2	J810X	208-230/460	220/380-415	3
3 A-2	XIIBL	115/208-230		1
3 A-2	J810X	208-230/460	220/380-415	3
	1810X	208-230/460	220/380-415	3
1501-2	J1013	230	The second secon	1
350A-2 □ ■ 5 A	7,010	208-230/460	220/380-415	3
	J910X	208-230/460	220/380-415	3
	01010	208-230/460	220/380-415	3
P355A	J1110A	208-230/460	220/380-415	3
PAPS3110M	J1210B	208-230/460	220/380-415	3
P6PS3110M	JD1100	208-230/460	220/380-415	3
				,

* No lubrication needed at start up. Bearings lubricated at factory.

* Motor is equipped with alemite fitting. Clean tip of fitting and apply grease gun. Use 1 to 2 stokes of high quality ball bearing grease.

	Considency	TYP•	Typical Greate				
	Medium	Uthium	Shell Dollum R				
	Hours of service per year		Suggested Rek Interval	ıb e			
	5.000		3 yecz				
i	בריסו ובניחוחכם	no-poloceAp	1 year				
	Sectional service Idle for a months	or more	of season) year beginning				
	במוזיים אים בשני במוץ פי יוספו בשני	ambienzi, Xications	6 months				

60 HZ FLOW DATA (CFM)

Žİ.

All performance figures relate to stock models. A few high pressure units may be available. Consult your local distributor,

Regenalr Model		PRESSURE													
Number	0"H ₂ O	20°H ₂ O	40°H2O	60°H2O	80°H2O	100"H ₂ O	Pressure "H ₂ O"								
R1	26	14					28								
ER2	42	26				***************************************	38								
R3105-1	52	38	14				42								
R3105-12	52		23				55								
R3305A-13	52	36	23				55								
LR4	90	70	50				52								
R5	145	130	100				65								
R6125-2	200	180					35								
R6325A-2	200	180	152				40								
_R6335A-2	205	175		135			70.								
R6350A-2	200	180	150	130	110	80	105								
TR6P335A	290	250		***************************************			30								
R6P350A	300	260	230	200		-	60								
R6P355A	300	260	230	200	160		 								
R7100A-2	420	380	340	310	280	230									
MOLLEGRADAL	485	452	. 420	380	330	200	115								
R6PS311OM	265	258	252	244	236	226	95 <u></u> 170 ·								

Regenair Model		VA	CUUM	T		Maximum
Number	0"H ₂ O	20"H ₂ O	40°H ₂ O	60°H2O	80°H ₂ O	Vacuum "H ₂ 0°
RI	25	14				26
R2	40	22		******************************		34
R3105-1	50	34	9		· · · · · · · · · · · · · · · · · · ·	40
R3105-12	51	34	20			50
R3305A-13	51	34"	20			50
R4	82	62	39			48
R5	140	115	90			60
R6125-2	190	155	125			45
R6325A-2	190	155	125.			45
R6335A-2	190	150	125	100		75
R6350A-2	190	180	150	100	07	90
R6P335A	270	230	***********************	· · · · · · · · · · · · · · · · · · ·		37
R6P350A	280	240	210	170		70
R6P355A	280	240	210	170	-100	86
R7100A-2	410	350	°, 3∞_,	250	170	90
R6PP311OM	470	425	375	320	220	80
R6PS31TOM	240	225	210	195	175	130

This number indicates the maximum static pressure differential recommended (with cooling air still flowing through unit). In general, units 1hp or less can be dead headed. Check with local representative or distributor to verify which models apply.

Operation of the blower above the recommended maximum duty will cause premature failure due to the build up of heat damaging the components.

Performance data was determined under the following conditions:


- 1) Unit in a temperature stable condition.
- 2) Test conditions: Inlet at density at 0.0750s, per cubic foot, (20°C(68°F), 29.92 h, Hg(14.7PSIA)).
- 3) Normal performance variations on the restance curve within +/- 10% of subsect data can be expected.
- 4) Specifications subject to change without notice.
- 5) All performance at 604z operation

REGENERATIVE BLOWER INJECTION SYSTEM DATA COLLECTION SHEET


15
=
1311
uilding
Pendleton Bu
Camp
MCB
SITE: M

СНЕСКЕР							
COMMENTS							
FILTER CHANGED (Y or N)							
BLOWER FUNCTIONING UPON ARRIVAL (Y or N)							
OUTLET PRESSURE (IN. WATER)							
OUTLET TEMP. (°F)			-				
INLET VACUUM (IN. WATER)							
TIME							
DATE							


APPENDIX B GEOLOGIC LOGS AND CHAIN OF CUSTODY FORMS




Project Camp Pendleton	Drill Company Cal Pac
Location Bldg 13115 Heating oil UST	Date Drilled 9/6/94
Job Number	Surface Elevation Not Surveyed
Geologist C. Loftenius	TOTAL DEPTH OF HOLE
Drill RigB-53 Hollow Stem Auger To 42'	Water Level No Groundwater Encountered




Project Camp Pendleton	Drill Company Cal Pac
Location Bldg 13115 Heating oil UST	Date Drilled 9/6/94
Job Number722406.58040	Surface Elevation Not Surveyed
Geologist C. Loftenius	TOTAL DEPTH OF HOLE16 feet bgs
	Water Level No Groundwater Encountered



Surveyed
35.5 feet bgs




Project Camp Pendleton	Drill CompanyCal Pac
Location Bldg 13115 Heating oil UST	Date Drilled9/7/94
Job Number	Surface Elevation Not Surveyed
Geologist C. Loftenius	TOTAL DEPTH OF HOLE 35.5 feet bgs
D F2 Hollow Cham Avenue To 25 Ft	



No Cross duplor Econoctored

DUES Hallow Stom Augor To SE E'



TOTAL DEPTH OF HOLE 30 feet bgs

Mater Lavel - No Groundwater Engountered

C. Loftenius

Driving R-53 Hollow Stem Auger To 30'

Geologist _

	RECORD
	$\overline{}$
	- CUSTOD
1	Ö
1	CHAIN
1	

14040 8 SOOD

				2017	68025	2033	*	٠,٠		\ }	e' -							e**)	,		•	On a
ANÂLYTICAL METHOD /	17=1-14/2/	SO THE STANDS OF	1918 1 1818 1 1 1 1 1 1 1 1 1 1 1 1 1 1	メメメメン マスメイン	1 + + + + + + 6153453 (MUCFRIM)	The strate		4/4/ 5 NEW 1	マンド かい たいまで						DATE	TIME L°C	E) DATE 9/8/6/1	322 SEN	DATE 9/9	TIME 1 4 (1) 110'd @ 40'S	5386651252 ENGINEERING-SCIENCE, 11008000	Shall - The ke aid & differed from other lac 15 10
	s	NO. OF NTAINERS	_	7	水平.	7									: (SKGNATUF	EX	: (SIGNATUR	yri	: (SIGNATUR	X.	398G	Come
PROJECT NAME	722406-58086 MCBCAMPPENNEROU	SAMPLERS/(Signatures)	SAMPLE 1.D.	CPI-VWI-20'	CP1-VW2-10'	CP1- MPA-36				1, 1,	Jan 19 1 19 19 19 19 1	*		140	 DATE Off RECEIVED BY: (SIGNATURE)	753 FED	DATE RECEIVED BY: (SIGNATURE)	TIME U. R. CONCHIV.	PP-6-Para	TIME 1441 TEDEX	F60 6X #	11299 1660
	288	SAMPLEF	MATRIX TYPE	2011	<u> </u>	4		·						X	IE INCUISHED BY (SIGNATURE) DATE	V 1	ELINOUISHED BY (SIGNATURE)		(SIGNATURE)	623	RELINGIOUHED TO	}
PROJECT NO.	35-90		TIME	979	2,80	0751		,		*			:		SHED BY (S	Y	SHED BY (S	7		2	-INJAC	A.
PRO	7224	8	DATE	ULPY	14/9	16/21	-								IE MOU	4	ENOU	FED-CX	ELINOUISHED BY	de	R. S.	}



PACK . 11. B.

Allani Cenagi Report To:

Bill To:

P.O. # / Billing Reference

11/1/21

Pace Client No.

CHAIN-OF-CUSTODY RECORD Analytical Request

Pace Project Manager

Pace Project No. プゲ

*Requested Due Date: // 27/14

				Project Name / No.	(VIII)	ti Me	~17	/) > *Requested Due Date: _/	122/1
ed By (PRINT):			SH:	PRESERVATIVES	ANALYSÉS /		1		
			L		REQUEST /	<i> </i>			
er Signature Date Sampled			ONT,	\	\ \ _	/	\		
			OF C	°(\ \ \			
SAMPLE DESCRIPTION	TIME MATRIX PACE NO.	PACE NO.	NO.	VOA HNC	\ \ \ \	/	\	/ REMARKS	{S
BKGUD-MP		3	X /	. 3	×	The second second		9409530 ol	10.0
THE THE PARTY CONTRACTOR OF THE PROPERTY OF TH	The state of the state of	the street of the	, d	TAKE DESCRIPTION	THE PARTY OF THE PROPERTY OF THE PARTY OF TH	DENNE WITH	and all		le le

1.1	8		Ħ.	£ 2.5	· .	; ;	ш.	
140407050	The state of the s	de de la constante de la const	The second secon	を記載さ	· Carolina C		DATE TIME	
() ()		•					DATE	
<u> </u>	*		0	i de alina	・ からの かいこう こうこう こうしゅ かんかい かんかい かんばん 大変な ないない かんしゅう アン・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	<u>}</u>	NOI	
		202	£.	<u> </u>		£	FFILIAT	
	жисты	FENDE	THOUSE			al Estatu	ACCEPTED BY / AFFILIATION	
Dir.	ay nata	191 TO	TOPES		こうこう きょうちょう かんかい アンドル 大変な ないない ないしゅう しゅうしゅう アンド・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	ienner I	NUMBER RELINQUISHED BY / AFFILIATION ACCEPTED BY / AF	
THE A	如西	HOLLO	N. TO			16. 110		
3a 5	TI DECEN	4				1.01	NO	
and the		35.5			**	E ME ALL	VFFILIATI	1
×I	D.	G.	E2 .				D BY / A	
		THE STATE	Mary Hard		The state of the s	e Haris	RELINQUISHED BY / AFFILIATION	
. W		in the same			1 m	ST. CIE	HELL	
		1	THOUSE IN		E-		TEM JMBER	
\		1	446		!	8	DATE	
SK6DD - ALL THE STATE OF THE ST	PRODUCTION OF THE PROPERTY OF	THE WINDS AND THE PROPERTY OF	CATOU HAS ON DIAME THE CONTROL OF THE SAME HAS BEEN AND THE SAME DESCRIPTION OF THE SAME PARTY OF THE	FERNOLES CONTROL OF THE PROPERTY OF THE PROP	Ř.	CHARLES HEALTS HEALTHAND CONTROL STRAIGHT TO THE STRAIGHT ON THE STRAIGHT OF T	T METHOD RETURNED / DATE NUMBER	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Name of Street	Hirory 3	200		i i	F. C. 164		
10.7				ACTION OF	i i i i i i i i i i i i i i i i i i i	F. Transfer	SHIPN OUT / DATE	
	artin a	-			CONTRACTOR OF THE PROPERTY OF	3216Ct		
Per di para			1			ic sach	BAILERS	
7	STATE OF THE STATE		den de la constanta	16 134	. je	HECK	/8	
7	- MAZZ	30	A. C.	And and and adding	C+	TO HE		
10°5				-		d is reported to the first to	os.	
DK				in a constant	Control of the second	in the second second	COOLER NOS.	
- 12	Fin :	Α"	<u>já 1</u>	· ·	ē _s	?		

nal Comments

	to .	A.*	à.,	h /	ès.
316	1	R *	E.	N	•
	1	13.7		£-	2.0
11	B.	65		2.1	. h.
~(¹)' I	2.		B-3		
4.0		6 0	54.5	3.	6
73	6	100			13
7.0	13.	MV.	13.77		Liber.
117		P 4	80%	PRO?	MIL.
	1	22	22	2	77
	13		120	74	2
4	EL		2.7	Pit.	5.
	\$4	Æc.	E.	F .	K-1
	1: 1	£.	N	130	4.
	5 .	5 .	in .	3.	1.5
2.	5 :	2	S	1	1.1
4			95.1	Gt.	
		127	1	10	12
		€.	25	E	N.
· '		\$3		100	
4		7.	35	(n)	
	E.	E .	4.		
	£ .	3:	100	7.	17.
		1	6.	Co.	1. 5
		3	1.1	8 -	
	ŕ.	3			F. :
	11	37	+ -	1	1
		£3	Č.	5	
	1,	34	;	1	
			N -	1	
	100	D		: .	1
	Ţ	K	9 -	THE PROPERTY OF THE PROPERTY O	The second of th
1 . A	\$:	2.	5.	2	23
13	Fi.	E	Y	14	
1 C X I	2.	S	1	1.	1.7
7 - 2	5, 2	8.	7.		100
1		Ex.	1		
1.6	1	26.7	1		10
	1.1	Ev.	E.	3	
71	P.	Di:	1.	P .	
1.77	10	Mer :	5.		5
1	1.		11.	L:	1 .
27	P	22.5	64.	6.	C
1 1	Æ.	ICS.	23	100	0,
	¥		2. 1	5.	
True 1	13.	4		E.	
	93.		1.	£.	2/
141	í.			6.0	51
N.	6	ž.	13	17	23
1	æ∵.	E3.	£9	3.	33
1 41	7		B .	4.7	En .
1 30	¥.	M	1	C =	
	2	A	F	Yr.	15.
II'U.	K	W	£	**	
Pager.	ē5 -	**	27.	£.	
1	3	Ç., .	200	t.	
1	E .	. 27	54	1	
1.74	2	.	,	6.5	32.
-		E.	₽,	V.	14
1,000	1	24	ř.	P	*.
AL A	E:	E/.	Is:	M.	A
-	S	Lie.	K		12.
The same	2	270	1	C	
With the		2	N.S.	8	0.
	1-	3		8:	2
Birthon 1	1	C.	1		3
127	No. 1	23	13.	1	
120	14 A	2.0		5).	E 60
Live :	T.	1	5.7	8.	è.
Marine	1	F .	(C)	1	1,0
F 22.	Z :	A.	3.5	Ε.	275
1. Z.	F.	4	\$.	N.	C.
110	K:		9	£	2
11.	12.5	0.	¥.	1.5	
- T	£.,	£.	C	1:	50.00
27	2.	£.	6	R.	
32	f	2.	C.	1.	
7 :	į 🐞		11	191	244
C 23	C .	P	ž .	E.	1
7. 1982	· .	Tr.	2.	1	100
ACC.	Ľ.	\$1	1	1	
Sugar.	E.	Ei.	5.		
32	b .	R.	51	ē	
150	Di.	100	51	F.	14
No.	8	1	ř.	4 :	1
	F		133	6	
16.	A."	24.	63.7	200	
12:00	1	33	P	1:	
See .	£ .	F		-	
5	7	4.		1.	
Jan. 1		4	şi.	5 .	
1 X 1	4.	¥ .	5.	4	
-	ř.	3.	3.5	15	
أ المالية	1.	2	2.1	101	
1925	12	27.	1	à.	37.
	₽ %	£	5.4	C .	2.
703		10 f. 7	100	5	S
1	7				
1		24.		Fr.	
The Mark Prend affine Note Harborn		是国际,19.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.			

CHAIN OF CUSTODY RECORD

240909500

	-	RELINOUISHED BY (SIGNATURE) DATE RECEIVED BY: (SIGNATURE)	194	HED BY (SIGNATURE) DATE - 8 -54										7/8/94 101. 2011 BICGND - MP) X	TYPE SAMPLE I.D.	SAM	58080 Building 13115
--	---	--	-----	---------------------------------	--	--	--	--	--	--	--	--	--	----------------------------------	------------------	-----	----------------------